
CITY OF BALTIMORE WET W SMOKE AND DYED W	Page _ / of _ 3	
Sewershed: PATAPSCO	Company: Savin Engineers	Date: 9-22-09
Test to be Performed:	Ground Condition:	Supervisor: Joe Mirabito
		winabito
Smoke: X Dyed Water:	Dry: X Damp: Wet:	Willabito

**Field Sketch:** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

tale!

HAZEL ST.



		ALTIMORE \ OKE AND D				ENT DECRE	E	Page 2	of <u>3</u>
Sewer	shed: <u>PATA</u>	PSCO		Compan	ıy: <u>SA</u> V	/IN		Date: 9/2	2/09
Test to	be Performed:			Ground	Condition			Supervisor:	TAM
	e: <u>X</u> Dy					p: We	<b>t</b> -		01111
OHIOR	. <u>A</u> Dy	ed Water		Diy	Duiii	p wo		Notifications Mad	do: X
Manho	le ID: <u>\$45</u> G	2_031MH		Test ID:	S1041	L-050		(Residents, Fire,	
	<b>Sketch:</b> (Showons, Street Nam						_		
Defect				Source	l		Drainage	, p	Photo
No.		Address		Type	Location	Sector	Area	Severity	Number
	1505 HAZEL S			3	8	2	4	3	P01
<u>'</u>	1303 TIAZEE O	1					<u> </u>	<u> </u>	101
				OBSERV	/ΔΤΙΩΝΙ	CODES			
	Source Type	Location	Sector	Severity	I	Source Type	Location	Ι	I
01	Main Sewer	Paved Concrete	Public	No Smoke	10	MH Frame Seal	Non-Paved		
	Service Line	Paved Asphalt	Private	Trace		Storm Drain	Field/Woods		
	Cleanout	Paved Other	vaic	Moderate			Alley		
	Downspout	Driveway	<del>                                     </del>	Major		Storm Manhole	Golf Course		
	Area Drain	Sidewalk	<del>                                     </del>	Major		Storm Ditch	Other		
	Driveway Drain	Curb	<del>                                     </del>	+		Excavation	Cuioi		
	Stairwell Drain	Yard- Front				Other			
	Foundation Drain	Yard-Back	<del>                                     </del>	+	10	Circi			
	Building Interior	Yard- Side	<del>                                     </del>	<del>                                     </del>					
00			1	1	1	ī		Ī	1

CITY OF BALTIMORE WET W SMOKE AND DYED W	Page <u>3</u> of <u>3</u>	
Sewershed: PATAPSCO	Company: Savin Engineers	Date: 9/22/09
Test to be Performed:	Ground Condition:	Supervisor: Joe Mirabito
Smake: V Dyad Water:	D V D 14/ .	
Smoke: X Dyed Water:	Dry: X Damp: Wet:	

**Field Sketch:** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



S1041-050-OB01-P01